



Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 1 of 7






Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.
For: Computer System with Bus Socket ...
Contact: Roger Fulghum/713-229-1707
Sheet 2 of 7





Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 3 of 7






Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681

Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707

Sheet 4 of 7







FIG 5





Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 5 of 7






Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681

Inventor: Miller et al.


For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 6 of 7



. Un Ξį

Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 7 of 7






FIG. 9